

Motorola Tablet Xoom 2 USB Port Repair

REPAIR ON MOTOROLA MZ617 USB PORT GUIDE

Written By: Abu Zubair



This document was generated on 2020-11-21 09:23:23 PM (MST).

INTRODUCTION

2 issues:

bricked battery and

USB port lifted on the MZ617

both now answered in a video I just uploaded below.

Direct charging batteries, reinforcing with Loctite Chipbonder helps with lifted USB port.

Z.

[video: https://www.youtube.com/watch?v=h4HJvOhQ9qo]

TOOLS:

• Pro Tech Toolkit (1)

This document was generated on 2020-11-21 09:23:23 PM (MST).

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-21 09:23:23 PM (MST).