IFIXIT

Lenovo Yoga Tablet 2 830-F Headphone Jack Replacement

This guide will cover the replacement of the headphone jack in the Lenovo Yoga 2 Tablet

Written By: Charles Rhode

This document was generated on 2020-11-25 11:58:01 AM (MST).

© iFixit — CC BY-NC-SA

www.iFixit.com

Page 1 of 4

TOOLS:

- Phillips #00 Screwdriver (1)
- Spudger (1)
- iFixit Opening Tools (1)

This document was generated on 2020-11-25 11:58:01 AM (MST).

Step 1 — Headphone Jack

- Remove the two 3mm screws on the back of the device with the Phillips Screwdriver #00 bit.

- Remove the 2mm screw with a Phillips #00 bit.

- Using the blue opening tool or spudger, gently remove the back cover to expose the interior of the tablet.

Step 2

- Remove the three 2mm screws on the back of the left speaker module with the Phillips Screwdriver #00 bit.

- Remove the ribbon cables connecting the boards to the other electrical components

- ⚠ Some of the ribbon cables are secured with clips, simply pry up the clips before sliding them out of the pin connectors.

This document was generated on 2020-11-25 11:58:01 AM (MST).

Step 3

- Gently remove the left speaker module.

- Replace the old left speaker module with the new left speaker module.

- ⚠ Be careful not to damage the ribbon cables on the new left speaker module while reassembling the device.

To reassemble your device, follow these instructions in reverse order.