

Repairing Samsung WF361BVBEWR ND Error Code

Samsung WF361BVBEWR A1 3.6 Cu. Ft. Capacity 8-Cycle High-Efficiency Front-Loading Washer With Internal Water Heater ND error code repair.

Written By: Brandon Johnson



This document was generated on 2020-11-24 03:12:42 PM (MST).

INTRODUCTION

Samsung WF361BVBEWR A1 3.6 Cu. Ft. Capacity 8-Cycle High-Efficiency Front-Loading Washer With Internal Water Heater will sometimes get a ND, Not Draining, error code. Here is a guide to help you clear it.


This document was generated on 2020-11-24 03:12:42 PM (MST).

Step 1 — Repairing Samsung WF361BVBEWR ND Error Code



• Remove filter from the lower left corner on the front of the washer

Step 2



• Wash debris from filter and reinstall. Once clean the washer should drain properly.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-24 03:12:42 PM (MST).