



Huawei Y300 Vibrator Replacement

Use this guide to replace the vibrator in your Huawei Y300.

Written By: Cordell



INTRODUCTION

In this guide we are going to replace the charging report on the Huawei ascend Y300 android smartphone. Before starting, it is a good idea to prepare an organized area to carry out the repair. It is also helpful to have a way of containing loose screws so they do not become lost.

TOOLS:


- [T4 Torx Screwdriver](#) (1)
 - [Tweezers](#) (1)
 - [Spudger](#) (1)
-

Step 1 — Vibrator




- Remove the back panel.

Step 2



- Remove the battery.

Step 3



- Use a T4 Torx screwdriver to remove the eight screws.


Step 4



- Pry the screen from the frame by utilizing a wedge.

⚠ Avoid scratching the case.

Step 5



- Use the tweezers to remove the vibrator from the device.

To reassemble your device, follow these instructions in reverse order.