

# Turtle Beach Ear Force XO Seven Slide Adjustment Replacement

Replace the slide adjustment mechanism.

Written By: Nancy Truong



This document was generated on 2020-11-21 10:37:04 AM (MST).

## **INTRODUCTION**

The slide adjustment lets you make the headset more comfortable. If it malfunctions, you can replace the slide adjustment mechanism in your Turtle Beach Ear Force XO Seven Headset with this guide.



# **TOOLS:**

- T6 Torx Screwdriver (1)
- Spudger (1)

# Step 1 — Take out the screws





Remove the two 1.0 cmTorx T6 screws using the matching Torx T6 screwdriver.

### Step 2 — Pop off the plastic mechanism





- Insert the spudger into the gap between the leather and plastic.
- After making sure you have a good grip, use the spudger to pry the two plastic pieces apart.

To reassemble your device, follow these instructions in reverse order.